



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah


DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program December 15, 2009

Reviewed: 

Mine Name: Velvet Extension	Permit Number: S/027/0067
Operator Name: Uranium One	Inspection Date: October 7, 2009
Inspector(s): T Munson	Time: 1:30 PM
Other Participants: Larry Trimble	Mine Status: Ins <u>ACTIVE</u>

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)
8. Soils
9. Revegetation

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$17700.00


Purpose of Inspection: Annual inspection

Inspection Summary: This site was seeded in Spring of 07 and Fall of 2008. All drill holes have been plugged as referenced in a previous inspection report.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The site is basically devoid of any vegetation except for some very sparse plants here and there. Hopefully, this winter will produce enough moisture to release this site.

Inspector's Signature 

TM:vs

cc: Larry.trimble@uranium1.com

ted_mcdougall@blm.gov

O:\M037-SanJuan\E0370133-VelvetExtension\inspections\lnsp-10072009.doc





Vegetation on site



Vegetation on site



Sparse vegetation